

Office Ph #
316-841-5395

Carr's HVAC
Service Price Book

3815 W. Douglas
Wichita KS 67213

NUMBER	REPAIR DESCRIPTION	Base PRIMARY	Base ADDL. REPAIR	AFTER HOURS PRIMARY	AFTER HOURS ADDL.	HDWE
GAS HEATING						
GEN122090	SINGLE TEMP SNAP ACTION LIMIT	\$102	\$82	\$142	\$114	\$23
GEN122095	ATO12, 13&14 ADJ TEMP SNAP ACTION LIMIT	\$115	\$91	\$154	\$123	\$35
GEN122100	SINGLE TEMP SNAP ACTION FAN SWITCH	\$102	\$82	\$142	\$114	\$23
GEN122105	ATO21 ADJ TEMP SNAP ACTION FAN SWITCH	\$115	\$91	\$154	\$123	\$35
GEN141004	THERMOCOUPLE 36" W/O REPAIR	\$102	\$82	\$142	\$114	\$23
GEN141007	THERMOCOUPLE 36" WITH REPAIR	\$63	\$51	\$82	\$66	\$23
GEN141010	THERMOCOUPLE 36" WITH BURNER OUT	\$32	\$25	\$35	\$28	\$23
GEN102090	GAS BURNER REMOVAL & CLEAN	\$80	\$63	\$119	\$95	\$0
GEN142PIL	CLEAN PILOT BURNER	\$80	\$63	\$119	\$95	\$0
GENSENSE	CLEAN FLAME SENSING ROD ""	\$52	\$42	\$78	\$63	\$0
GEN141104	TEST/ADJUST MANIFORD PRSSURE	\$52	\$42	\$78	\$63	\$0
GEN141170	PILOT RE-LIGHT ONLY/NO REPAIRS	\$39	\$32	\$59	\$48	\$0
GEN142001	CLEAN OUT 90% FLUE	\$80	\$63	\$119	\$95	\$0
GEN142002	RESET MANUAL LIMIT AND TEST	\$52	\$42	\$78	\$63	\$0
GEN141355	GAS LEAK SEARCH / ACCESSIBLE	\$80	\$63	\$119	\$95	\$0
GEN141356	TIGHTEN GAS LINE/ACCESSIBLE	\$39	\$32	\$59	\$48	\$0
GEN141357	TIGHTEN GAS LINE/NONACCESSIBLE	\$80	\$63	\$119	\$95	\$0
GENHTEX01	CARBON MONOXIDE TEST (NO DIAGNOSTIC)	\$138	\$110	\$197	\$158	\$19
GEN141998	LIGHT FURN CLEANING - NO SOOT	\$127	\$101	\$186	\$149	\$9
GEN141ROD	ROD OUT HEAT EXCHANGER	\$249	\$200	\$368	\$295	\$13
GEN142000	POWER VAC HEAT EXCHANGER	\$510	\$407	\$748	\$597	\$35
GEN153000	THOROUGHLY CLEAN FLOOR FURN	\$162	\$130	\$242	\$194	\$4
GEN153001	THOROUGHLY CLEAN WALL FURN	\$162	\$130	\$242	\$194	\$4
GENL36-850	CAM-STAT PILOT RE-IGNITE KIT	\$209	\$167	\$248	\$199	\$129
GEN141103	GENERIC GAS REG. 1/2" OR 3/4"	\$231	\$185	\$310	\$248	\$73
GENPTUBE	REPLACED ALUMINUM PILOT	\$102	\$82	\$142	\$114	\$23
GEN141104	UNIV. GAS VALVE REPLACE (HSI/DSI)	\$335	\$268	\$415	\$331	\$177
GEN141105	UNIV. GAS VALVE REPLACE (STND PILOT)	\$325	\$259	\$404	\$323	\$167
GEN141106	UNIV. GAS VALVE W/T-COUPLE REPLACE	\$358	\$287	\$444	\$355	\$187
GEN141110	FACTORY GAS VALVE REPLACE	\$471	\$377	\$569	\$455	\$273
GEN141175	GENERIC PILOT BURNER W/O REPAIR	\$168	\$134	\$228	\$182	\$49
GEN141176	GENERIC PILOT BURNER WITH REPAIR	\$129	\$102	\$168	\$134	\$49
GEN141180	GENERIC 750 MILIVOLT GEN. CARTRIDGE	\$159	\$128	\$199	\$159	\$81
GEN141186	G-60 VALVE REPLACEMENT 24V	\$402	\$323	\$482	\$386	\$244
GEN141187	G-60 IGN SYSTEM WITH DAMPER PLUG	\$452	\$362	\$531	\$425	\$293
GEN141205	GEN. FAN/LIMIT REPLACE. 5"-11"	\$182	\$147	\$223	\$178	\$104

Office Ph #
316-841-5395

Carr's HVAC
Service Price Book

3815 W. Douglas
Wichita KS 67213

NUMBER	REPAIR DESCRIPTION	Base PRIMARY	Base ADDL. REPAIR	AFTER HOURS PRIMARY	AFTER HOURS ADDL.	HDWE
GEN1205W	GEN. FAN/LIMIT REP. 5"-11" W/HEATER	\$219	\$176	\$259	\$207	\$140
GEN141206	CAMSTAT FAN/LIMIT 3" TEMP SENSOR	\$202	\$162	\$242	\$194	\$123
GEN141207	CAMSTAT FAN/LIMIT 7" TEMP SENSOR	\$202	\$162	\$242	\$194	\$123
GEN141336	36" FLEX GAS LINE * REPL/INSTALL	\$130	\$105	\$171	\$137	\$52
GEN141348	48" FLEX GAS LINE * REPL/INSTALL	\$142	\$113	\$181	\$144	\$62
GENGASCO	REPLACE 1/2" - 3/4" GAS COCK	\$76	\$61	\$101	\$81	\$23
GEN141364	REP. 1/2" OR 3/4" BLK PIPE NIP. TO 6"	\$87	\$70	\$127	\$101	\$9
GEN141365	REP. 1/2" OR 3/4" BLK PIPE ELBOW	\$87	\$70	\$127	\$101	\$9
GEN141367	REP. 1/2" OR 3/4" BLK PIPE ST. EL	\$87	\$70	\$127	\$101	\$9
GEN141368	REPL. 1/2" OR 3/4" BLK PIPE 45 EL	\$87	\$70	\$127	\$101	\$9
GEN141369	REPL. 1/2" OR 3/4" BLK PIPE PLUG	\$24	\$19	\$32	\$25	\$9
GEN141370	REPL. 1/2" OR 3/4" BLK PIPE CAP	\$24	\$19	\$32	\$25	\$9
GEN141371	REPL. 1/2" OR 3/4" BLK PIPE I/R	\$48	\$38	\$67	\$54	\$9
GEN141372	REPL. 1/2" OR 3/4" BLK PIPE COUPLING	\$87	\$70	\$127	\$101	\$9
GEN141373	REPL. 1/2" OR 3/4" BLK PIPE I/R	\$87	\$70	\$127	\$101	\$9
GEN141374	REPL. 1/2" OR 3/4" BLK PIPE TEE	\$87	\$70	\$127	\$101	\$9
GEN141375	REPL. 1/2" OR 3/4" BLK PIPE UNION	\$52	\$42	\$72	\$57	\$13
GEN141376	REBUILD BLK PIPE LINE	\$235	\$188	\$315	\$252	\$77
GENHTEX07	WARR HORIZ HT EXCH 40M-75M	\$500	\$400	\$736	\$589	\$25
GENHTEX10	WARR HORIZ HT EXCH OVER 75M	\$658	\$526	\$974	\$779	\$25
GENVTEX07	WARR VERT HT EXCH. 40M-75M	\$500	\$400	\$736	\$589	\$25
GENVTEX10	WARR VERT HT EXCH OVER 75M	\$658	\$526	\$974	\$779	\$25
GENXPEX10	WARR HT EXCH PKG UNITL 40M-75M	\$662	\$530	\$978	\$783	\$29
GENXPEZ12	WARR HT EXCH PKG UNIT OVER 75M	\$820	\$657	\$1,216	\$973	\$29
GENHTEX02	ADDITIONAL PERSON*HT EXCH/PULL	\$119	\$95	\$178	\$143	\$0
GENHTEX04	MANUF SHIPPING/HANDLING CHARGE	\$80	\$63	\$119	\$95	\$0
GLC271YOO	NORTON 271Y HOT SURFACE IGNITOR	\$172	\$138	\$213	\$170	\$94
HWL2A1025	Q302A-1025 PILOT GENERATOR	\$159	\$128	\$199	\$159	\$80
HWL421005	Y86 GAS VALVE & SPARK KIT	\$909	\$728	\$1,080	\$865	\$565
HWL421020	GAS VALVE FOR Y86 KIT* REPLMNT	\$614	\$491	\$752	\$601	\$339
HWL421025	Y86 CONTROL MODULE* REPLMNT	\$594	\$475	\$662	\$530	\$458
HWL421030	Y86 IGNIITOR SENSOR ASSEM* REPL	\$249	\$198	\$293	\$235	\$156
HWL421035	Y86 IGN. CABLE * REPLACEMENT	\$189	\$152	\$224	\$178	\$121
HWL421100	VR8450M4045 LP GAS VALVE	\$587	\$469	\$724	\$579	\$312
HWL0U1000	S8910U1000 IGNITION MODULE	\$550	\$440	\$618	\$495	\$411