

Office Ph #
316-841-5395

Carr's HVAC
Service Price Book

3815 W. Douglas
Wichita KS 67213

NUMBER	REPAIR DESCRIPTION	Base PRIMARY	Base ADDL. REPAIR	AFTER HOURS PRIMARY	AFTER HOURS ADDL.	HDWE
OTHER MOTOR & FAN REPAIRS						
GEN133004	PULLEY THRU 4" (4L)	\$134	\$108	\$173	\$139	\$56
GEN133008	PULLEY 4.5" THRU 8" (4L)	\$166	\$133	\$206	\$164	\$87
GEN133012	PULLEY 8.5" THRU 12" (4L)	\$209	\$167	\$248	\$199	\$129
GEN133315	1.5-3 TON BLWR WHEEL W/O MTR C/O	\$258	\$206	\$338	\$269	\$100
GEN133350	3.5-5 TON BLWR WHEEL W/O MOTR C/O	\$287	\$230	\$367	\$293	\$129
GEN133351	1.5-3 TON BLWR WHEEL W/MTR C/O	\$139	\$111	\$159	\$128	\$100
GEN133352	3.5-5 TON BLWR WHEEL W/MTR C/O	\$168	\$135	\$188	\$151	\$129
GEN133354	1.5-3 TON BLWR WHEEL BELT DRIVE	\$350	\$280	\$469	\$374	\$113
GEN133355	3.5-5 TON BLWR WHEEL BELT DRIVE	\$393	\$315	\$511	\$410	\$156
FAN BLADE W/MOTOR CHANGE						
GEN133405	1.5 TON UNIT	\$105	\$85	\$125	\$100	\$66
GEN133410	2 THRU 2.5 TON UNIT	\$116	\$92	\$135	\$109	\$77
GEN133415	3 TON UNIT	\$116	\$94	\$137	\$109	\$77
GEN133420	3.5 TON UNIT	\$124	\$99	\$143	\$115	\$83
GEN133425	4 TON UNIT	\$143	\$114	\$163	\$130	\$104
GEN133430	5 TON UNIT	\$166	\$133	\$185	\$148	\$127
FAN BLADE W/O MOTOR CHANGE						
GEN133455	1.5 TON UNIT	\$185	\$148	\$244	\$195	\$66
GEN133460	2 THRU 2.5 TON UNIT	\$195	\$156	\$254	\$204	\$77
GEN133465	3 TON UNIT	\$196	\$157	\$256	\$204	\$77
GEN133470	3.5 TON UNIT	\$202	\$162	\$262	\$210	\$83
GEN133475	4 TON UNIT	\$221	\$177	\$281	\$225	\$104
GEN133480	5 TON UNIT	\$244	\$196	\$304	\$243	\$127
GEN152045	CLEAN BLOWER WHEEL	\$137	\$110	\$204	\$163	\$4
GEN52045C	CLEAN BLOWER WHEEL @ CAR WASH	\$167	\$133	\$245	\$196	\$9
GEN52045D	CLEAN BLOWER W/MTR CHANGE	\$52	\$42	\$78	\$63	\$0
GEN133550	DIRECT DRIVE MTR BRACKET REPLACEMENT	\$235	\$187	\$314	\$250	\$77
GEN133556	FACTORY MTR BRACKET REPLACEMENT	\$235	\$188	\$315	\$252	\$77

Office Ph #
316-841-5395

Carr's HVAC
Service Price Book

3815 W. Douglas
Wichita KS 67213

NUMBER	REPAIR DESCRIPTION	Base PRIMARY	Base ADDL. REPAIR	AFTER HOURS PRIMARY	AFTER HOURS ADDL.	HDWE
GEN133575	17"-26" FAN BELT W/BLWR REPAIRS	\$29	\$24	\$35	\$29	\$16
GEN133576	26.5"-56" FAN BELT W/BLWR REPAIRS	\$32	\$25	\$38	\$30	\$19
GEN133577	56.5"-90" FAN BELT W/BLWR REPAIRS	\$48	\$39	\$54	\$44	\$35
GEN133580	17"-26" FAN BELT W/O BLWR REPAIRS	\$56	\$46	\$76	\$61	\$16
GEN133581	26.5"-56" FAN BELT W/BLWR REPAIRS	\$59	\$47	\$78	\$63	\$19
GEN133582	56.5-90" FAN BELT W/O BLWR REPAIR	\$76	\$61	\$95	\$76	\$35
GEN133583	BELT ADJUSTMENT W/O BLWR REPAIR	\$39	\$32	\$59	\$48	\$0
GEN133584	TEST FULL LOAD AMPS & ADJUST PULLEY	\$52	\$42	\$78	\$63	\$0
GEN133590	REMOUNT & ALIGNMENT OF BLWR WHEEL	\$83	\$67	\$123	\$99	\$4
GEN133595	REMOUNT & ALIGNMENT OF FAN BLADE	\$83	\$67	\$123	\$99	\$4
GEN133596	REMOVE & BRAZE FAN HUB/BRACKET	\$167	\$133	\$245	\$196	\$9
GEN133605	3 EAR MTR MOUNT KIT W/MTR REP.	\$78	\$63	\$99	\$78	\$39
GEN133610	3 EAR MTR MOUNT KIT W/O MTR REP.	\$158	\$127	\$218	\$173	\$39
GEN133640	RAINSHIELD WITH MOTOR CHANGE	\$27	\$22	\$28	\$23	\$23
GEN133645	SL000031 RAINSHIELD ALONE ""	\$102	\$82	\$142	\$114	\$23
GEN133650	MOTOR MOUNT CUSHIONS ONLY	\$151	\$120	\$206	\$164	\$39
GEN133655	REMOUNT OR SHIM A MOTOR	\$83	\$67	\$123	\$99	\$4
GEN133660	REPLACE INSERT BEARING 1/2"-1" EACH	\$310	\$248	\$429	\$343	\$73
GEN133665	REPLACE INSERT BEARING 1/2"-1" BOTH	\$429	\$343	\$587	\$469	\$113
GEN133670	BRONZE PILLOW BEARING THRU 1" (EACH)	\$269	\$215	\$388	\$310	\$32
GEN133675	BRONZE PILLOW BEARING THRU 1" (BOTH)	\$364	\$291	\$522	\$417	\$48
GENSHAFT	ADD FOR SHAFT REPLACEMENT THRU 1"	\$142	\$113	\$181	\$144	\$62
GEN133680	PILLOW BALL BEARING THRU 1" (EACH)	\$324	\$259	\$443	\$354	\$87
GEN133685	PILLOW BALL BEARING THRU 1" (BOTH)	\$467	\$373	\$625	\$500	\$151
GEN133690	SHAFT LOCKING COLLAR	\$65	\$52	\$87	\$71	\$16
GEN133691	SHAFT ADAPTER BUSHINGS	\$65	\$52	\$87	\$71	\$16
GENSLG0031	SLG0052 SMALL RAIN SHIELD	\$15	\$13	\$18	\$14	\$13
RUU53060X	MOUNT PLATE W/MOTOR C/O	\$87	\$70	\$106	\$86	\$48
RUU530602	MOUNT PLATE W/O MOTOR C/O	\$166	\$133	\$225	\$181	\$48
RUU530603	MOUNTING CABLES W/MOTOR C/O	\$83	\$67	\$102	\$82	\$43
RUU530604	MOUNTING CABLES W/O MOTOR C/O	\$162	\$130	\$221	\$177	\$43