

Office Ph #  
316-841-5395

Carr's HVAC  
Service Price Book

3815 W. Douglas  
Wichita KS 67213

NUMBER	REPAIR DESCRIPTION	Base PRIMARY	Base ADDL. REPAIR	AFTER HOURS PRIMARY	AFTER HOURS ADDL.	HDWE
<b>FUSES &amp; BREAKERS</b>						
GELTHQL3P	G.E. THQL TYPE 3 POLE BRKR 20-60A	\$207	\$166	\$226	\$181	\$167
GEN127001	RESET & TEST BRKR/NO REPAIRS	\$39	\$32	\$59	\$48	\$0
GEN127030	FRN 0-30 AMP FUSES W/O REPAIR	\$35	\$28	\$48	\$39	\$9
GEN127032	FRN 0-30 AMP FUSES WITH REPAIR	\$22	\$16	\$28	\$22	\$9
GEN127060	FRN 35-60 AMP FUSES W/O REPAIR	\$43	\$35	\$57	\$46	\$16
GEN127062	FRN 35-60 AMP FUSES WITH REPAIR	\$29	\$24	\$35	\$29	\$16
GEN30600	600V FUSE 0-30 AMP	\$63	\$51	\$76	\$61	\$35
GEN60600	600V FUSE 35-60 AMP	\$71	\$57	\$83	\$67	\$43
GEN100600	600V FUSE 70-100 AMP	\$108	\$86	\$121	\$96	\$81
GEN127130	GENERIC CIRCUIT BRKR 0-30 AMP 1 POLE	\$156	\$124	\$195	\$156	\$77
GEN127132	GENERIC CIRCUIT BRKR 0-30 AMP 2 POLE	\$209	\$167	\$248	\$199	\$129
GEN127160	GENERIC CIRCUIT BRKR 35-60 AMP 2 POLE	\$209	\$167	\$248	\$199	\$129
GEN127564	RAINTITE DISCONNECT 30A W/O FUSES	\$181	\$144	\$240	\$192	\$62
GEN127565	RAINTITE DISCONNECT 60A W/O FUSES	\$194	\$154	\$259	\$207	\$62
GEN127180	TIGHTEN CONN. @ FUSE/BREAKER	\$39	\$32	\$59	\$48	\$0
GEN127566	GLASS CONTROL FUSE 0-15 AMP	\$32	\$25	\$44	\$35	\$4
TRA047600	FUS-0476 RED CAP FUSE	\$65	\$52	\$85	\$67	\$25
TRABWAX66	CONTROL FUSE	\$65	\$52	\$85	\$67	\$25
COLCONFUS	COLEMAN 3 OR 5A CONTROL FUSE	\$32	\$25	\$44	\$35	\$4
GEN127175	FACTORY CONTROL FUSES	\$65	\$52	\$85	\$67	\$25
GEN31-294	G31-294 CONTROL FUSE HOLDER	\$52	\$42	\$72	\$57	\$13
GEN143050	GENERIC FUSIBLE LINK	\$100	\$80	\$139	\$111	\$22
GEN143051	SUPCO MICRO TEMP FUSE LINK L37-941	\$109	\$87	\$148	\$119	\$29
GENPIGT10	1/2' A/C PIGTAIL REPLACE #10 AWG	\$121	\$97	\$161	\$129	\$43
GENPIGT08	3/4' A/C PIGTAIL REPLACE #8 AWG	\$135	\$109	\$176	\$140	\$57
GENWHIP	1/2 OR 3/4' WHIP W/DISCON. REPL.	\$70	\$56	\$76	\$61	\$57